

Series WE08 Two Way Brass Ball Valve

Specifications - Installation and Operating Instructions



The SERIES WE08 incorporates a full port 2-piece brass ball valve for great flow rates with minimal pressure drop. The valve features a blowout proof stem for added safety, reinforced PTFE seats and seals for longer life, and a brass ball for better performance. Actuators are direct mounted creating a compact assembly for tight spaces.

The Series WE08 can be configured with either an electric or pneumatic actuator. Electric actuators are available in weatherproof or explosion-proof, a variety of supply voltages, and two-position or modulating control. Two-position actuators use the supply voltage to drive the valve open or closed, while the modulating actuator accepts a 4 to 20 mA input for valve positioning. Actuators feature thermal overload protection and permanently lubricated gear train.

The pneumatic double acting actuator uses an air supply to drive the valve open and closed. The actuator has two supply ports, with one driving the valve open and the other driving the valve closed. Spring return pneumatic actuators use the air supply to open the valve and internally loaded springs return the valve to the closed position. Also, between the air supply ports for opening and closing the valve, actuators are constructed of anodized and epoxy coated aluminum for years of corrosion free service.

SPECIFICATIONS VA

VALVEElectric "TD" and "MD" SeriesService: Compatible liquids and gases.Power Requirements: 110 VAC, 220Body: 2-piece.VAC, 24 VAC, or 24 VDC (MD modelsLine Sizes: 1/2 to 2".not available in 24 VDC).End Connections: Female NPT.Power Consumption: See instructionPressure Limits: 600 psi (41 bar) WOG.manual.Wetted Materials: Body, ball, and stem:Cycle Time (per 90°): TD01 4 s; MD0Brass; Seat, seal, and packing: PTFE.Duty Rating: 85%.Temperature Limits: -20 to 425°F (-30to s; TD02: 20 s).Other Materials: O-ring: NBR; Handle, stem nut, ferrule: SS; Handle Sleeve:Duty Rating: NEMA 4X (IP67).Vinyl; Body and cap: Nickle plated.Temperature Limits: -22 to 140°F (-3	
Body: 2-piece.VAC, 24 VAC, or 24 VDC (MD models not available in 24 VDC).Line Sizes: 1/2 to 2".VAC, 24 VAC, or 24 VDC (MD models not available in 24 VDC).End Connections: Female NPT.Power Consumption: See instruction manual.Pressure Limits: 600 psi (41 bar) WOG.Power Consumption: See instruction manual.Wetted Materials: Body, ball, and stem: Brass; Seat, seal, and packing: PTFE. Temperature Limits: -20 to 425°F (-30 to 220°C).Duty Rating: 85%. Enclosure Rating: NEMA 4X (IP67). Housing Material: Powder coated aluminum.Other Materials: O-ring: NBR; Handle, stem nut, ferrule: SS; Handle Sleeve: Vinyl; Body and cap: Nickle plated.UAC, 24 VAC, or 24 VDC (MD models not available in 24 VDC).Power Consumption: See instruction manual.Cycle Time (per 90°): TD01 4 s; MD0 10 s; TD02: 20 s).Duty Rating: 85%. Enclosure Rating: NEMA 4X (IP67).Housing Material: Powder coated aluminum.Temperature Limits: -22 to 140°F (-3	
Line Sizes: 1/2 to 2". End Connections: Female NPT. Pressure Limits: 600 psi (41 bar) WOG. Wetted Materials: Body, ball, and stem: Brass; Seat, seal, and packing: PTFE. Temperature Limits: -20 to 425°F (-30 to 220°C). Other Materials: O-ring: NBR; Handle, stem nut, ferrule: SS; Handle Sleeve: Vinyl; Body and cap: Nickle plated. Inot available in 24 VDC). Power Consumption: See instruction manual. Cycle Time (per 90°): TD01 4 s; MD0 10 s; TD02: 20 s). Duty Rating: NEMA 4X (IP67). Housing Material: Powder coated aluminum. Temperature Limits: -22 to 140°F (-3	
End Connections: Female NPT. Pressure Limits: 600 psi (41 bar) WOG.Power Consumption: See instruction manual.Wetted Materials: Body, ball, and stem: Brass; Seat, seal, and packing: PTFE. Temperature Limits: -20 to 425°F (-30 to 220°C).Power Consumption: See instruction manual.Cycle Time (per 90°): TD01 4 s; MD0 10 s; TD02: 20 s).Duty Rating: 85%. Enclosure Rating: NEMA 4X (IP67).Other Materials: O-ring: NBR; Handle, stem nut, ferrule: SS; Handle Sleeve: Vinyl; Body and cap: Nickle plated.Housing Material: Powder coated aluminum.Temperature Limits: -22 to 140°F (-3Temperature Limits: -22 to 140°F (-3	
Pressure Limits: 600 psi (41 bar) WOG.manual.Wetted Materials: Body, ball, and stem:Cycle Time (per 90°): TD01 4 s; MD0Brass; Seat, seal, and packing: PTFE.10 s; TD02: 20 s).Temperature Limits: -20 to 425°F (-30Duty Rating: 85%.to 220°C).Dther Materials: O-ring: NBR; Handle,Other Materials: O-ring: NBR; Handle,Housing Material: Powder coatedstem nut, ferrule: SS; Handle Sleeve:aluminum.Vinyl; Body and cap: Nickle plated.Temperature Limits: -22 to 140°F (-3	
Wetted Materials: Body, ball, and stem: Brass; Seat, seal, and packing: PTFE. Temperature Limits: -20 to 425°F (-30 to 220°C).Cycle Time (per 90°): TD01 4 s; MD0 10 s; TD02: 20 s).Uty Rating: 85%. Enclosure Rating: NEMA 4X (IP67).Other Materials: O-ring: NBR; Handle, stem nut, ferrule: SS; Handle Sleeve: Vinyl; Body and cap: Nickle plated.Uty Rating: 22 to 140°F (-30 Lots and the stem nut, ferrule: SS; Handle Sleeve:Vinyl; Body and cap: Nickle plated.	
Brass; Seat, seal, and packing: PTFE. 10 s; TD02: 20 s). Temperature Limits: -20 to 425°F (-30 to 220°C). Duty Rating: 85%. Other Materials: O-ring: NBR; Handle, stem nut, ferrule: SS; Handle Sleeve: Housing Material: Powder coated aluminum. Vinyl; Body and cap: Nickle plated. Temperature Limits: -22 to 140°F (-3	
Temperature Limits: -20 to 425°F (-30 to 220°C). Duty Rating: 85%. Other Materials: O-ring: NBR; Handle, stem nut, ferrule: SS; Handle Sleeve: Vinyl; Body and cap: Nickle plated. Housing Material: Powder coated aluminum. Temperature Limits: -22 to 140°F (-3 Temperature Limits: -22 to 140°F (-3	1:
to 220°C). Other Materials: O-ring: NBR; Handle, stem nut, ferrule: SS; Handle Sleeve: Vinyl; Body and cap: Nickle plated. Enclosure Rating: NEMA 4X (IP67). Housing Material: Powder coated aluminum. Temperature Limits: -22 to 140°F (-3	
Other Materials: O-ring: NBR; Handle, stem nut, ferrule: SS; Handle Sleeve: Vinyl; Body and cap: Nickle plated. Housing Material: Powder coated aluminum. Temperature Limits: -22 to 140°F (-3	
stem nut, ferrule: SS; Handle Sleeve: Vinyl; Body and cap: Nickle plated. Temperature Limits: -22 to 140°F (-3	
Vinyl; Body and cap: Nickle plated. Temperature Limits: -22 to 140°F (-3	
to 60°C))
to 60°C).	
ACTUATORS Electrical Connection: 1/2" female N	PT.
Pneumatic "DA" and "SR" Series Modulating Input: 4 to 20 mA.	
Type: DA series is a double acting and Standard Features: Manual override,	
SR series is a spring return (rack and position indicator, and TD models com	Э
pinion). with two limit switches.	
Normal Supply Pressure: DA: 40 to 115	
psi (2.7 to 7.9 bar); SR: 80 psi (5.5 bar). Electric "TI" and "MI" Series	
Maximum Supply Pressure: 120 psi Power Requirements: 110 VAC, 220	
(8.6 bar). VAC, 24 VAC, 24 VDC.	
Air Connections: DA02 to DA03: 1/4" Power Consumption: See instruction	
female NPT; SR02 to SR04: 1/4" female manual.	
NPT. Cycle Time (per 90°): See instruction	
Housing Material: Anodized aluminum manual.	
body and epoxy coated aluminum end Duty Rating: See instruction manual.	
caps. Enclosure Rating: NEMA 7, designed	
Temperature Limits: -40 to 176°F (-40 to meet hazardous locations: Class I,	
to 80°C). Group C & D; Class II, Group E, F & G	;
Accessory Mounting: NAMUR Division I & II.	
standard. Housing Material: Powder coated	
aluminum.	
Temperature Limits: -40 to 140°F (-4)
to 60°C).	
Electrical Connection: 1/2" female N	PT.
Modulating Input: 4 to 20 mA.	
Standard Features: Position indicator	
and two limit switches.	

A DIVISION OF W.E. ANDERSON DWYER INSTRUMENTS, INC. P.O. BOX 373 • MICHIGAN CITY, INDIANA 46360, U.S.A.

Phone: 219/879-8000 Fax: 219/872-9057

www.dwyer-inst.com e-mail: info@dwyermail.com

MODE	L CHART					
			Popular	Popular	Popular NEMA 4X	Popular NEMA 4X
		Popular	Double Acting	Spring Return	Two Position	Modulating
	Cv	Hand Operated	Pneumatic	Pneumatic	Electric	Electric
Size	(gal/min)	Model	Model	Model	(110 VAC) Model	(110 VAC) Model
1/2″	16	WE08-CHD00	WE08-CDA02	WE08-CSR02	WE08-CTD01-A	WE08-CMD01-A
3/4″	40	WE08-DHD00	WE08-DDA02	WE08-DSR03	WE08-DTD01-A	WE08-DMD01-A
1″	65	WE08-EHD00	WE08-EDA02	WE08-ESR03	WE08-ETD01-A	WE08-EMD01-A
1-1/4″	90	WE08-FHD00	WE08-FDA03	WE08-FSR03	WE08-FTD01-A	WE08-FMD01-A
1-1/2″	135	WE08-GHD00	WE08-GDA03	WE08-GSR03	WE08-GTD01-A	WE08-GMD01-A
2″	251	WE08-HHD00	WE08-HDA03	WE08-HSR04	WE08-HTD02-A	WE08-HMD01-A

VALVE BILL OF MATERIALS





ltem	Description	Material	Qty
1	Body	Brass	1
2	Сар	Brass	1
3	Ball	Brass	1
4	Ball seat	PTFE	2
5	Joint gasket	PTFE	1
6	Stem	Brass	1
7	Thrust washer	NBR	1
8	O-ring	NBR	1
9	Stem packing	PTFE	1-2
10	Gasket	PTFE	1
11	V sealing	AISI 304	1
12	Lock nut	AISI 304	1
13	Stopper, bolt & Nut	AISI 304	1
14	Stem nut	AISI 304	1
15	Handle	PVC	1
16	Handle cover	AISI 304	1
17	Ferrule	AISI 304	1

VALVE DIMENSIONAL DRAWING



MODEL CHAR	ODEL CHART												
		ØA	Ø D1	Ø D2		Ø Ra	Ø Rb	S	L	Н	W	M1	Cv
Model	Size	in (mm)	in (mm)	in (mm)	ISO	in (mm)	in (mm)	in (mm)	in (mm)	in (mm)	in (mm)	in (mm)	(gal/min)
WE08-CHD00	1/2″	1/2″	-	1-27/64″	F03	-	R7/64" (R2.5)	23/63" (9)	2-11/64″	1-33/64″	5-23/64″	M12X1.5	16
		(13)		(36)					(55)	(38)	(140)		
WE08-DHD00	3/4″	3/4″	1-31/32″	-	F05	R1/8" (R3)	-	7/16″ (11)	2-51/64″	1-5/8″	6-5/16″	M14X1.5	40
		(19)	(50)						(71)	(41)	(160)		
WE08-EHD00	1″	63/64″	1-31/32″	-	F05	R1/8" (R3)	-	7/16″ (11)	3-15/64″	1-49/64″	6-5/16″	M14.1.5	65
		(25)	(50)						(82)	(45)	(160)		
WE08-FHD00	1-1/4″	1-17/64″	1-31/32″	2-49/64″	F05/F07	R11/64" (R4)	R1/8" (R3)	9/16" (14)	3-37/64″	2-1/8″	7-9/32″	M18X1.5	90
		(32)	(50)	(70)					(90.8)	(54)	(185)		
WE08-GHD00	1-1/2″	1-1/2" (38)	1-31/32″	2-49/64″	F05/F07	R11/64" (R4)	R1/8" (R3)	9/16" (14)	4-1/16″	2-21/64″	7-9/32″	M18X1.5	135
			(50)	(70)					(103)	(59)	(185)		
WE08-HHD00	2″	1-31/32″	1-31/32″	2-49/64″	F05/F07	R11/64" (R4)	R1/8" (R3)	9/16″ (14)	4-49/64″	2-21/32″	7-9/32″	M18X1.5	251
		(50)	(50)	(70)					(121)	(67)	(185)		



DOUBLE ACTING PNEUMATIC ACTUATOR 1-1/4″ NPT 1/2" 3/4" 2-1/2" 1″ 1-1/2" 2 3″ В 4-5/8′ 4-3/4 5-1/2 5-3/4′ 6-7/8′ 6-7/8″ 8-3/8 9″ 116 mm 119 mm 141 mm 146 mm 174 mm 174 mm 212 mm 229 mm С 2-3/8" 2-3/8" 2-3/4" 2-3/4" 3-1/4" 3-1/4" 3-3/4″ 4″ 61 mm 61 mm 71 mm 71 mm 82 mm 82 mm 94 mm 101 mm D 3-1/2″ 2-1/4" 2-5/8" 3-1/8" 4-1/8" 4-7/8" 5-3/4" 6-1/2" 58 mm 66 mm 79 mm 90 mm 105 mm 124 mm 146 mm 164 mm Е 4-5/8″ 4-5/8″ 5-3/4″ 5-3/4″ 6-5/8″ 6-5/8″ 7-7/8″ 8-1/4" 116 mm 116 mm 145 mm 145 mm 169 mm 169 mm 201 mm 209 mm F 1-3/4″ 2″ 1-1/2″ 1-1/2" 1-5/8″ 1-5/8" 1-3/4″ 2″ 37 mm | 37 mm | 41 mm 46 mm 46 mm 52 mm 41 mm 52 mm

SPRI	NG RETU	JRN PNE	UMATIC A	CTUATO	R			
NPT	1/2″	3/4″	1″	1-1/4″	1-1/2″	2″	2-1/2″	3″
в	5″	5-1/8″	6-1/8″	6-3/8″	7-1/4″	8″	9-5/8″	10″
	128 mm	131 mm	157 mm	162 mm	186 mm	204 mm	245 mm	254 mm
С	2-3/4″	2-3/4″	3-1/4″	3-1/4″	3-3/4″	4″	4-3/4″	4-3/4″
	71 mm	71 mm	82 mm	82 mm	94 mm	101 mm	122 mm	122 mm
D	2-1/4″	2-5/8″	3-1/8″	3-1/2″	4-1/8″	4-7/8″	5-3/4″	6-1/2″
	58 mm	66 mm	79 mm	90 mm	105 mm	124 mm	146 mm	164 mm
E	5-3/4″	5-3/4″	6-5/8″	6-5/8″	7-7/8″	8-1/4″	10-7/8″	10-7/8″
	145 mm	145 mm	169 mm	169 mm	201 mm	209 mm	275 mm	275 mm
F	1-5/8″	1-5/8″	1-3/4″	1-3/4″	2″	2-1/8″	2-1/2″	2-1/2″
	41 mm	41 mm	46 mm	46 mm	52 mm	55 mm	64 mm	64 mm

W/ ELECTRIC ACTUATOR



NPT 1/2" 3/4″ 1-1/4" 1-1/2 2-1/2 2″ 3 1 5-1/8 в 5 6-1/8" 6-3/8 7-1/4 8 9-5/8 10 128 mm 131 mm 157 mm 162 mm 186 mm 204 mm 245 mm 254 mm С 2-3/4" 2-3/4″ 4-3/4″ 4-3/4″ 3-1/4" 3-1/4" 3-3/4" 4″ 71 mm 71 mm 82 mm 82 mm 94 mm 101 mm 122 mm 122 mm D 2-5/8″ 4-7/8″ 5-3/4″ 2-1/4″ 3-1/8″ 3-1/2″ 4-1/8" 6-1/2″ 58 mm 66 mm 79 mm 90 mm 105 mm 124 mm 146 mm 164 mm Е 5-3/4″ 5-3/4″ 6-5/8″ 6-5/8" 7-7/8″ 8-1/4″ 10-7/8″ 10-7/8″ 169 mm 169 mm 201 mm 209 mm 275 mm 275 mm 145 mm 145 mm F 1-5/8" 1-5/8″ 1-3/4" 1-3/4″ 2" 2-1/8″ 2-1/2″ 2-1/2" 41 mm 41 mm 46 mm 46 mm 52 mm 55 mm 64 mm 64 mm

ELECTRIC ACTUATOR

EXPL	OSION-F	PROOF E	LECTRIC	ACTUAT	OR			
NPT	1/2″	3/4″	1″	1-1/4″	1-1/2″	2″	2-1/2″	3″
В	5″	5-1/8″	6-1/8″	6-3/8″	7-1/4″	8″	9-5/8″	10″
	128 mm	131 mm	157 mm	162 mm	186 mm	204 mm	245 mm	254 mm
С	2-3/4″	2-3/4″	3-1/4″	3-1/4″	3-3/4″	4″	4-3/4″	4-3/4″
	71 mm	71 mm	82 mm	82 mm	94 mm	101 mm	122 mm	122 mm
D	2-1/4″	2-5/8″	3-1/8″	3-1/2″	4-1/8″	4-7/8″	5-3/4″	6-1/2″
	58 mm	66 mm	79 mm	90 mm	105 mm	124 mm	146 mm	164 mm
E	5-3/4″	5-3/4″	6-5/8″	6-5/8″	7-7/8″	8-1/4″	10-7/8″	10-7/8″
	145 mm	145 mm	169 mm	169 mm	201 mm	209 mm	275 mm	275 mm
F	1-5/8″	1-5/8″	1-3/4″	1-3/4″	2″	2-1/8″	2-1/2″	2-1/2″
	41 mm	41 mm	46 mm	46 mm	52 mm	55 mm	64 mm	64 mm

W/ EXPLOSION-PROOF ELECTRIC ACTUATOR



B

PNEUMATIC ACTUATOR

Note: For optimal operation, pneumatic actuators should be run with a supply of clean, lubricated air.

Spring Return Actuator Operation

Air to PORT 2 (the left hand port) causes the actuator to turn counterclockwise (CCW). Loss of air to PORT 2 causes air to exhaust and the actuator turns clockwise (CW). This is the FAIL CLOSE operation.

Double Acting Actuators Operation

Air to PORT 2 (the left hand port) causes the actuator to turn counterclockwise (CCW). Air to PORT 1 (the right hand port) causes the actuator to turn clockwise (CW).

Pneumatic Actuator Maintenance

Routine maintenance of pneumatic actuator:

- Keep the air supply dry and clean
- Keep the actuator surface clean and free from dust
- · Periodic checks should be done to make sure all fittings are tight
- Pneumatic actuators are supplied with lubrication to last the entire life span of the actuator under normal operating conditions.

The outer surface of the pneumatic actuator should be clean to avoid friction or corrosion. All fittings and connections should be tight to prevent leaks during operation. Check the bolts mounting the valve to the actuator to make sure they have not come loose during shipping or installation. Make sure the valve and actuator are not rubbing or jamming against other components during operation. The actuator should be inspected annually to make sure all fittings and bolts are tight and nothing has come loose during operation.

Disassembling Pneumatic Actuators

WARNING Before beginning disassembly, ensure that the air supply to the actuator has been disconnected, all accessories have been removed, and that the actuator has been disassembled from the valve.

- Loosen the end cap fasteners (23) with a wrench (size varies depending on actuator model). On the spring return actuator, alternate 3 to 5 turns on each fastener until the springs are completely decompressed. Use caution when removing the cap since the springs are under load until the fasteners are fully extended.
- 2. Remove the pinion snap ring (13) with a lock ring tool. The indicator (12) may now be removed.
- Turn the pinion shaft (2) counter clockwise until the pistons are at the full end of travel. Disengage the pistons (15) from the pinion. (Note: Low pressure air--3 to 5 psi MAXIMUM--might be required to force the pistons completely from the body.) Note the position of the pistons before removing them from the actuator body.
- 4. Remove the pinion through the bottom of the actuator. The actuator is now completely disassembled. Pneumatic A

Failures	Inspection Items	Corrective Action			
Pneumatic	1. Check the solenoid valve. Is the	1. Replace the solenoid			
actuator	coil burnt out or is the solenoid	valve coil or remove debris.			
won't operate	spool?				
	2. The actuator will not move	2. Disassemble the actuator,			
	because of debris in the gears.	clean the debris and			
		reassemble the actuator.			
	3. The pneumatic line to the	3. Replace pneumatic line to			
	actuator is distorted or smashed.	the actuator.			
	4. The pneumatic line is frozen	4. Warm the pneumatic lines			
	because of low temperatures and	and remove moisture from			
	moisture.	supply lines.			
Pneumatic	1. The air supply pressure is	1. Increase the air supply			
actuator runs	insufficient.	pressure and look for leaks			
slowly		in the supply pressure			
		pipeline.			
	2. Are other pneumatic devices	2. Increase the air supply			
	consuming the air required for the	or reduce the number of			
	actuator to operate?	devices operating at the			
		same time.			
	3. The pneumatic actuator is	3. Replace the actuator with			
	undersized for the application.	a larger actuator.			

Reassembling Pneumatic Actuators



G Be sure the actuator surfaces are free of debris and scratches before reassembling.

- 1. Apply a light film of grease to all O-rings and the pinion before replacing.
- Put the pinion (2) back through the actuator with the flats of the pinion shaft running parallel with the body.
- 3. When reassembling the actuator, make sure that the piston racks are square to the actuator body and returned to their original orientation. (Note: The normal operation of all spring return pneumatic actuators is FAIL CLOSED. To change the orientation to FAIL OPEN, rotate the racks 180° to create a reverse operation.
- 4. When replacing springs in a spring return actuator, ensure that the springs are replaced in their identical position in the end cap from which they were removed. (Note: In some circumstances, you might want to change the standard 80 pound spring set to fit your application and available air pressure.)
- 5. Seal the end caps with a petroleum lubricant and bolt to actuator body.
- Check the seal of the actuator by covering seal areas (pinion, end caps) with soapy water and using low pressure air to the actuator to ensure that no bubbles are produced.

Pneumatic Actuators Bill of Materials



Part			
Number	Quantity	Part Name	Material
1	1	Cylinder	Extruded aluminum alloy
2	1	Output shaft	Stainless steel
3	1	O-ring	Fluorine silicon rubber
4	1	Bearing	Nylon46
5	1	Adjusting cam	Stainless steel
6	1	Thrust bearing	Nylon46
7	1	Bearing	Nylon46
8	1	O-ring	Fluorine silicon rubber
9	1	Bearing	Nylon46
10	1	Gasket	Stainless steel
11	1	Damping ring	Stainless steel
12	1	Position indicator	PPPP+30%GF
13	1	Screw	PPPP+30%GF
14	4	Position indicating	PPPP+30%GF
		Inserts	
15	2	Piston	Casting aluminum alloy
16	2	Guide ring	Nylon46
17	2	O-ring	Fluorine silicon rubber
18	2	Guide ring	Fluorine-carbon composite material
19	5 to 12	Spring assembly	Alloy spring steel
20	2	O-ring	Fluorine silicon rubber
21	1	Left end cap	Casting aluminum alloy
22	1	Right end cap	Casting aluminum alloy
23	8	End cap bolt	Stainless steel
24	2	O-ring	Fluorine silicon rubber
25	2	Gasket	Stainless steel
26	2	Nut	Stainless steel
27	2	Adjusting Bolt	Stainless steel

MODEL CH	MODEL CHART											
	DA Do	uble-Ac	tion Ou	tput To	rque (Ib	-in)						
	Air Pre	Air Pressure										
Model	40 psi	40 psi 50 psi 60 psi 70 psi 80 psi 90 psi 100 psi 110 psi 115 psi										
ACT-DA01	49	61	74	86	98	110	123	135	142			
ACT-DA02	104	130	155	181	207	233	259	285	300			
ACT-DA03	182	228	274	319	365	411	456	502	529			
ACT-DA04	302	377	453	528	603	679	754	830	875			
ACT-DA05	396	495	594	693	792	891	990	1089	1148			
ACT-DA06	567	709	851	993	1135	1277	1419	1561	1649			
ACT-DA07	845	1056	1267	1478	1690	1901	2112	2323	2450			
ACT-DA08	1497	1871	2245	2619	2993	3367	3742	4116	4340			
ACT-DA09	2253	2816	3379	3942	4506	5069	5632	6195	6533			

MODEL CH	ART														
		SR Si	SR Single Acting Pneumatic Actuator (Ib-in)												
		Air Pr	Pressure												
		70 ps	i	80 ps	i	90 ps	i	100 p	si	110 p	si	115 p	si	Spring	Torque
	Spring	0°	90°	0°	90°	0°	90°	0°	90°	0°	90°	0°	90°	0°	90°
Model	Quantity	Start	End	Start	End	Start	End	Start	End	Start	End	Start	End	Start	End
ACT-SR02	10	111	86	137	112	163	138	189	164	215	189	231	205	96	70
ACT-SR03	10	199	143	245	189	291	235	336	280	382	326	409	353	176	120
ACT-SR04	10	348	254	424	330	499	405	575	481	650	556	695	601	274	180
ACT-SR05	10	430	312	529	411	628	510	727	609	826	708	885	767	381	263
ACT-SR06	10	608	458	750	599	891	741	1033	883	1175	1025	1260	1110	536	386
ACT-SR07	10	783	663	994	874	1206	1085	1417	1297	1628	1508	1755	1635	817	696
ACT-SR08	10	1682	1208	2056	1583	2430	1957	2804	2331	3178	2705	3403	2930	1416	938
ACT-SR09	10	2303	1483	2866	2046	3429	2609	3992	3173	4556	3736	4894	4074	2363	1575
ACT-SR10	10	3479	2274	4337	3133	5195	3991	6053	4849	6911	5707	7426	6222	3549	2407

ELECTRIC ACTUATORS

Electric Installation

- 1. Operate valve manually and place in the open position.
- 2. Remove any mechanical stops the valve might have. (DO NOT REMOVE ANY PARTS NECESSARY FOR THE PROPER OPERATION OF THE VALVE, SUCH AS THE PACKING GLAND, PACKING NUT, ETC.)
- Ensure that the actuator output shaft and valve stem are aligned properly. If they are not, operate the valve manually until they are correct.
- 4. Remove actuator cover.
- Bring power to the actuator. CAUTION: Make sure power is OFF at the main box.
- Wire the actuator per the diagram attached to the inside of the cover. Special actuators (those with positioner boards, etc.) will have diagrams enclosed inside the cover.
- Securely tighten bolts used to mount the actuator to a mounting bracket or directly to the valve mounting pad if it is ISO5211 compliant.
- Cycle the unit several times and check the open and closed positions of the valve. Cams are pre-adjusted at the factory; due to the variety of valve designs and types however, slight adjustments might be required.
 Replace cover and tighten screws.

- To Set The Open Position
 Cycle the valve to the open position by applying power to terminals. The top cam and switch control this position. In the open position, the set screw in the top cam will be accessible.
- 2. If the valve is not open completely:
- a. Slightly loosen the set screw on the top cam.
- b. Rotate the cam clockwise (CW) by hand until the switch makes contact. Contact is made when a slight click can be heard. By making incremental CW movements of the top cam, the valve can be positioned precisely in the desired position.
- c. When the top cam is set, tighten the set screw securely.

3. If the valve opens too far:

- a. Apply power to terminals. This will begin to rotate valve CW. When valve is fully open and in the exact position desired, remove power from actuator.
- b. Loosen the set screw in the top cam.
- c. Rotate the top cam counterclockwise (CCW) until the switch arm drops off the round portion of the cam onto the flat section. A slight click can be heard as the switch changes state.
- d. Continue applying power to terminals until valve is in the desired position.

To Set The Closed Position

- Apply power to terminals to move the valve toward the closed position. The bottom cam and switch control the closed position. In the closed position, the set screw in the bottom cam will be accessible.
- 2. If the valve is not closed completely:
 - a. Slightly loosen the set screw on the bottom cam.
 - b. Rotate the cam counterclockwise (CCW) by hand until the switch makes contact. Contact is made when a slight click can be heard. By making incremental CCW movements of the bottom cam, the valve can be positioned precisely in the desired position.
 - c. When the top cam is set, tighten the set screw securely.
- 3. If the valve closes too far:
 - a. Apply power to terminals. This will begin to rotate valve CCW. When valve is fully closed and in the exact position desired, remove power from actuator.
 - b. Loosen the set screw in the top cam.
 - c. Rotate the top cam clockwise (CW) until the switch arm drops off the round portion of the cam onto the flat section. A slight click can be heard as the switch is no longer making contact with the round part of the cam.
 - d. Continue applying power to terminals until valve is in the desired position.

Wiring Diagrams for TI01-A to TI06-A1: 110 VAC, TI01-B to TI06-B: 220 VAC, TI01-C to TI06-C: 24 VAC



Wiring Diagrams for TI01-D to TI06-D: 24 VDC



Wiring Diagrams for MI01-A to MI06-A1: 110 VAC, MI01-B to MI06-B: 220 VAC, MI01-C to MI06-C: 24 VAC







Wiring Diagrams for TD01-D to TD06-D: 24 VDC







Note: To speed up installation of the control wires to the ACT-MDXX modulating actuator, it is recommended to remove the control module from the actuator. The control module can be removed by removing the two mounting screws on the left and right of the control module. Install the control wires to the correct terminal points and then reinstall the control module.

Electric Actuator Maintenance

Once the actuator has been properly installed, it requires no maintenance. The gear train has been lubricated and in most cases will never be opened.

Duty Cycle Definition

"Duty Cycle" means the starting frequency. Formula: Running Time ÷ (Running Time + Rest Time) x 100% = duty cycle -> Rest Time = Running Time x (1 - duty cycle) ÷ duty cycle

For example: The running time is 15 seconds

30% duty cycle 15 x [(1 - 30%) / 30%] = 35 -> The rest time will be 35 seconds 75% duty cycle 15 x [(1 - 75%) / 75%] = 5 -> The rest time will be 5 seconds

If the duty cycle is higher, the rest time will be shortened, which means the starting frequency will be higher.

Thermal Overload

All actuators are equipped with thermal overload protection to guard the motor against damage due to overheating.

Mechanical Overload

All actuators are designed to withstand stall conditions. It is not recommended to subject the unit to repeated stall conditions.

Explosion-Proof Electric Actuators



 DO NOT under any circumstances remove the cover of the actuator while in a hazardous location. Removal of the cover while in a hazardous location could cause ignition of hazardous atmospheres.

- DO NOT under any circumstances use an explosion-proof electric actuator in a hazardous location that does not meet the specifications for which the actuator was designed.
- Always verify that all electrical circuits are de-energized before opening the actuator.
- Always mount and cycle test the actuator on the valve in a non-hazardous location.
- When removing the cover, care must be taken not to scratch, scar of deform the flame path of the cover and base of the actuator, since this will negate the NEMA rating of the enclosure.
- 6. When replacing the cover, take care that the gasket is in place to assure proper clearance after the cover is secured.
- 7. All electrical connections must be in accordance with the specifications for which the unit is being used.
- 8. Should the unit ever require maintenance, remove from the hazardous location before attempting to work on the unit.

If the actuator is in a critical application, it is advisable to have a standby unit in stock.

Electric Actuators Performance Rating

TD01				
Voltage	110 VAC	220 VAC	24 VAC	24 VDC
Cycle Time	4 s	4 s	4 s	4 s
Duty Cycle (Two-Position)	85%	85%	85%	85%
AMP Draw	0.24 A	0.16 A	0.28 A	1.28 A
Torque (in-lb)	177	177	177	177

MD01			
Voltage	110 VAC	220 VAC	24 VAC
Cycle Time	10 s	10 s	10 s
MD01 Duty Cycle (Modulating)	85%	85%	85%
AMP Draw	0.24 A	0.16 A	1.28 A
Torque (in-lb)	265	265	265

TD02 and MD02 (MD Not Available in 24 VDC)				
Voltage	110 VAC	220 VAC	24 VAC	24 VDC
Cycle Time	20 s	20 s	20 s	20 s
Duty Cycle (Two-Position)	85%	85%	85%	85%
Duty Cycle (Modulating)	85%	85%	85%	-
AMP Draw	0.24 A	0.16 A	1.28 A	1.28 A
Torque (in-lb)	442	442	442	442

TD03 and MD03 (MD Not Available in 24 VDC)				
Voltage	110 VAC	220 VAC	24 VAC	24 VDC
Cycle Time	30 s	30 s	30 s	30 s
Duty Cycle (Two-Position)	85%	85%	85%	85%
Duty Cycle (Modulating)	85%	85%	85%	-
AMP Draw	0.57 A	0.35 A	2.03 A	2.03 A
Torque (in-lb)	885	885	885	885

TD04 and MD04 (MD Not Available in 24 VDC)				
Voltage	110 VAC	220 VAC	24 VAC	24 VDC
Cycle Time	30 s	30 s	30 s	30 s
Duty Cycle (Two-Position)	85%	85%	85%	85%
Duty Cycle (Modulating)	85%	85%	85%	-
AMP Draw	0.65 A	0.37 A	3.57 A	3.57 A
Torque (in-lb)	1770	1770	1770	1770

TD05 and MD05 (MD Not Available in 24 VDC)				
Voltage	110 VAC	220 VAC	24 VAC	24 VDC
Cycle Time	30 s	30 s	30 s	30 s
Duty Cycle (Two-Position)	85%	85%	85%	85%
Duty Cycle (Modulating)	85%	85%	85%	-
AMP Draw	1.12 A	0.57 A	5.13 A	5.13 A
Torque (in-lb)	3540	3540	3540	3540

TD06 and MD06 (MD Not Available in 24 VDC)				
Voltage	110 VAC	220 VAC	24 VAC	24 VDC
Cycle Time	45 s	45 s	45 s	45 s
Duty Cycle (Two-Position)	85%	85%	85%	85%
Duty Cycle (Modulating)	85%	85%	85%	-
AMP Draw	1.18 A	0.60 A	6.04 A	6.04 A
Torque (in-lb)	5210	5210	5210	5210

TI01				
Voltage	110 VAC	220 VAC	24 VAC	24 VDC
Cycle Time	2.5 s	2.5 s	2.5 s	2.5 s
Duty Cycle (Two-Position)	25%	25%	25%	25%
Full Load AMP Draw	0.64	0.32	0.4	0.4
Torque (in-lb)	100	100	100	100

TI02 and MI01, MI02				
Voltage	110 VAC	220 VAC	24 VAC	24 VDC
Cycle Time (Two Position)	5 s	5 s	5 s	5 s
Cycle Time (Modulating)	10 s	10 s	5 s	5 s
Duty Cycle (Two-Position)	25%	25%	25%	25%
Duty Cycle (Modulating)	75%	75%	75%	75%
Full Load AMP Draw	0.38	0.18	0.7	0.7
Torque (in-lb)	200	200	200	200

TI03 and MI03				
Voltage	110 VAC	220 VAC	24 VAC	24 VDC
Cycle Time (Two-Position)	5 s	5 s	5 s	5 s
Cycle Time (Modulating)	10 s	10 s	5 s	5 s
Duty Cycle (Two-Position)	25%	25%	25%	25%
Duty Cycle (Modulating)	75%	75%	75%	75%
Full Load AMP Draw	0.38	0.18	0.7	0.7
Torque (in-lb)	300	300	300	300

TI04 and MI04				
Voltage	110 VAC	220 VAC	24 VAC	24 VDC
Cycle Time (Two-Position)	10 s	10 s	10 s	10 s
Cycle Time (Modulating)	20 s	20 s	10 s	10 s
Duty Cycle (Two-Position)	25%	25%	25%	25%
Duty Cycle (Modulating)	75%	75%	75%	75%
Full Load AMP Draw	0.38	0.18	0.9	0.9
Torque (in-lb)	400	400	400	400

TI05 and MI05				
Voltage	110 VAC	220 VAC	24 VAC	24 VDC
Cycle Time (Two-Position)	15 s	15 s	15 s	15 s
Cycle Time (Modulating)	30 s	30 s	15 s	15 s
Duty Cycle (Two-Position)	25%	25%	25%	25%
Duty Cycle (Modulating)	75%	75%	75%	75%
Full Load AMP Draw	0.38	0.18	0.7	0.7
Torque (in-lb)	675	675	675	675

TI06 and MI06				
Voltage	110 VAC	220 VAC	24 VAC	24 VDC
Cycle Time (Two-Position)	15 s	15 s	15 s	15 s
Cycle Time (Modulating)	30 s	30 s	15 s	15 s
Duty Cycle (Two-Position)	25%	25%	25%	25%
Duty Cycle (Modulating)	75%	75%	75%	75%
Full Load AMP Draw	0.38	0.18	1.1	1.1
Torque (in-lb)	1000	1000	1000	1000

MAINTENANCE/REPAIR

Upon final installation of the Series WE, only routine maintenance is required. The Series WE is not field serviceable and should be returned if repair is needed. Field repair should not be attempted and may void warranty.

WARRANTY/RETURN

Refer to "Terms and Conditions of Sale" in our catalog and on our website. Contact customer service to receive a Return Goods Authorization number before shipping the product back for repair. Be sure to include a brief description of the problem plus any additional application notes.

W.E. ANDERSON A DIVISION OF DWYER INSTRUMENTS, P.O. BOX 373 • MICHIGAN CITY, INDIANA 46360, U.	INC. .S.A.	Phone: 219/879-8000 Fax: 219/872-9057	www.dwyer-inst.com e-mail: info@dwyermail.com
©Copyright 2017 Dwyer Instruments, Inc.	12 Printed in U.S.A. 1	1/17	FR# 444338-00 Rev. 1